TECHNICAL AND SERVICE BULLETIN

NO: 38

DATE: APRIL 1992

TO: Subject: **ALL KOMPAC DEALERS**

CALIBRATION PROCEDURES FOR KOMPAC UNITS

KOMPAC FORM TO METERING PRESSURE

- 1. Loosen set screws on top of end frames.
- 2. Turn metering gauges to the OFF position.
- 3. Insert two strips of 20 # bond paper between the form and metering rollers.
- 4. Turn metering gauges to achieve a firm, even drag on both sides.
- 5. Once an even drag is achieved, retighten set screws on top of both end frames.
- 6. Remove slotted cap screws from metering guages.
- 7. Loosen inner set screws and turn metering gauge to the number 1 position.
- 8. Tighten inner set screws and then replace cap screws on metering gauge.

Note: Final metering gauge settings should be adjusted between 2 and 3.

KOMPAC FORM ROLLER TO PLATE

- 1. Remove Kompac safety cover.
- 2. Apply small smear of ink on Kompac form roller, across full width.
- 3. Replace Kompac safety cover.
- 4. Turn on power and start press. Allow ink to run in.
- 5. When Kompac rollers are completely ink covered, shut off press.
- 6. Drop Kompac in contact with the plate to produce a stripe across the plate.
- 7. This stripe should be between 1/8" and 3/16" wide and even across the entire width of the plate. If not, adjust per installation procedure for the press model you are working with.

Note: Final stripe setting should be checked in the impression position of the press.

KOLORMATE OSCILLATOR ROLLER TO METERING

- 1. Remove Kolormate safety cover.
- 2. Apply small smear of ink on Kompac form roller, across full width.
- 3. Replace Kolormate safety cover.
- 4. Turn on power and start press. Allow ink to run in.
- 5. When Kompac rollers are completely ink covered, shut off press.
- 6. Using a 3/32" alien wrench, carefully turn pressure screws until they hit alignment blocks. Tighten no more than one full turn after this point. Tighten locking nuts.
- 7. Stripe between oscillator and metering should be 1/8".

Note: When metering pressure is separated for long storage or cleaning, remove oscillator pressure.

Thank you for your continued support.

Michael Pek Technical Representative

C