

TECHNICAL BULLETIN INDEX

NUMBER	DATE	SUBJECT
80	December 2000	Hamada DU-34-II Update
79	June 2000	Warranty Claim Procedure
78	February 2000	Kompac II and T Part Number Chart
77	December 1999	Maintaining The Kompac Dampening System
76	October 1999	Townsend T-51 Update
75	June 1999	Hamada Update
74	April 1999	AB Dick Improvement
73	February 1999	Warranty Claim Procedure
72	December 1998	Kompac Model Change
71	August 1998	New Universal Fountain Solution Kompac All
70	June 1998	Ryobi 3302 Unit Change
69	March 1998	Kompac Units for Hamada Presses
68	February 1998	Hamada RS/VS Satellite Heads
67	November 1997	Maintaining the Kompac & Approved Products
66	October 1997	AB Dick 98,99 Contin. Dampening Systems
65	August 1997	Mounting bracket Change M-1819-1
64	June 1997	Kompac Replacement Rollers
63	April 1997	Kompac Cleaning Seals
62	February 1997	Multi 1860,1960,4600 MC and GPC Models
61	December 1996	Oscillator Change
60	October 1996	Maintaining The Kompac & Approved Products
59	August 1996	Ryobi 3200 Press Change
58	April 1996	Multi 1650 MC and GPC Press Models
57	February 1996	Calibration Procedures
56	December 1995	End Frame Bearing Change
55	October 1995	Imitation Kompac Parts
54	August 1995	Warranty Claim Procedure
53	June 1995	Kompac Replacement Rollers
52	April 1995	Obsolete Parts
51	February 1995	End Frame Bearing Change 700
50	September 1994	Maintaining The Kompac & Approved Products
50-A	March 1994	Transparent Cover
49	March 1994	AB Dick Gear Change
48	December 1993	Tie Plate Upgrade Kits
47	October 1993	End Frame Bearing Change
46	August 1993	Kompac Cleaning Seals
45	June 1993	Kompac Replacement Rollers
44	April 1993	ATF Chief and Gestetner Lift Links
43	February 1993	End Frame Bearing Change
42	December 1992	Maintaining the Kompac & Approved Products
41	October 1992	Kompac Replacement Rollers
40-A	September 1992	M1819 & RY330 Serial Number Cutoffs

40	August 1992	Calibration Procedure for M1819-1
39	June 1992	Updated Kompac Model List
38	April 1992	Calibration Procedure All Models
37	February 1992	Safety Covers on Multi 1250
36	October 1991	Seal Burn in
35	September 1991	Maintaining the Kompac & Approved Products
34	August 1991	Updated Models List
33	July 1991	Kompac T Water Level Control
32	May 1991	Kompac Replacement Rollers
31	April 1991	Kompac For Toko and Multi
30	March 1991	Maintaining the Kompac T
29	February 1991	Calibration Procedure Kompac T
28	January 1991	ATF and Gestetner Brackets
27	December 1990	Calibration All Models
26	October 1990	Hamada Safety Cover Price Correction
25	September 1990	Warranty Claim Procedure
24	August 1990	Maintaining the Kompac
23	July 1990	Hamada 600 Safety Cover Kit
22	June 1990	New RY2728/3200 Bracket Kit
21	May 1990	Kolormate Retrofit Update
20	February 1989	AB Dick Wire Guard Brackets
19	September 1988	New Kompac Kolormate
18	February 1988	Rollers with Pressed on Bearings
17	November 1987	Ryobi Plate Clamp
16	August 1987	New ATF Brackets
15	March 1986	Safety Decals
14	October 1985	ATF Chief Presses
13	June 1985	AB 5060 Safety Cover Kit
12	February 1985	Parts Inventory Offer
11	December 1984	ATF 15/15g 17/17g Lift Kit
10	September 1984	Super Rubber Rejuvenator / Caution
09	August 1984	Seal Backing Plate Design Change
08	May 1984	Small Parts Kits
07	May 1984	Warranty Replacement Reimbursement
06	April 1984	Design Change AB 5060
05	February 1984	Kompac II Inventory Special
04	February 1983	Introduction of Kompac II
03	April 1982	Installation Tips M125 ML Unit
02	April 1981	Installation Tips AB 5060 Unit
01	April 1981	5 Steps for Effective Installation