

TECHNICAL AND SERVICE BULLETIN

No. 17

Date: NOVEMBER 1987

Ryobi 2800 Plate Clamp Part Number

When installing the left and right hand pivot plates on older model Ryobi and Itek machines, the plate clamp assembly will have to be removed.

The following is a list of the parts that would be needed to use a modern plate clamp assembly on an old Ryobi.

<u>PART #</u>	<u>NAME</u>	<u>QTY. NEEDED</u>
5290-29-113-2	Frame	1
5320-52-420	Bracket	1
5320-52-410	Ryobi 2800 Lever	1
5320-52-414	Roller	1
5290-29-313	Lever Washer	1
9721-0700-08	E-Ring E-7	1
9721-0400-14	E-Ring E-7	1
9716-0600-14	Washer	1
9670-0612-08	Socket Bolt M6 x 12	2

The customer needs to use the following from this old plate clamp assembly.

<u>PART #</u>	<u>NAME</u>	<u>QTY. NEEDED</u>
# Varies for Color	Ball Grip	1
6290-33-534	Spring	1
9670-0612-08	Socket Bolt M6 x 12	3

The customer may also have to trim the frame plate to fit the older Ryobi. He would need to remove about 1/2" from the 90 degree corner of the plate.

VARN PRODUCTS CO., INC. 175 Route 208, Oakland, New Jersey 07436 • (201) 337-3600

NEW JERSEY • ILLINOIS • TEXAS • CALIFORNIA • CANADA • ENGLAND • W. GERMANY