

KOMPAC TECHNICAL UPDATE

NO: 49


DATE: MARCH 1994

**TO: ALL KOMPAC
DEALERS**

**SUBJECT: AB DICK GEAR
CLUTCH CHANGE**

Effective February 1, 1994, Graph Tech will use the same clutch for all AB Dick Kompac units produced. The part number affected by this change is 92810 for all existing AB 9875 Kompac units. When replacement of this gear clutch is required, you can order part number 90710. This kit will include new gear clutch part number 92940 and two (2) hex head screws, part number 91867. Shorter hex head mounting screws are required to keep screws from interfering with the new gear clutch. Models AB 8800, AB 9800, AB 3850 and AB 8090 are not effected by this change. These models were produced with the new gear clutch and shorter hex screws. The price for this replacement kit will remain the same as part number 92810 at \$55.00 list and \$37.40 dealer cost.

NOTE: Existing AB 5060 Kompac units will still require part number 92810. If the Kompac unit you are changing over to the new style gear is below serial number 20,000, you should speak to a technical representative before placing a parts order at 1-800-541-5702.



Use only genuine Kompac parts and remember to take advantage of our 50% Waste Reduction Program.

Thank you for your continued support.

Michael Pek
Technical Service Representative
Kompac Division